

Shop Set, Contact And Emergency Repair: Field Maintenance, Less Power And Map Only

SC: 4940-95-A21
NSN: 4940-00-754-0737
LIN: T26030
TM: 9-4910-409-12

System Description

Provides the necessary components to accomplish on-site welding & general automotive/vehicle repair. Intended for use by direct support maintenance personnel.

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

n/a

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568)
rock-pm-skot@conus.army.mil